Appendix 1

Extract from Historic England Register of Heritage at Risk (2016)



| SITE NAME: | Church of St Mary Stratford Bow, Bow Road, Poplar E3 |
|--------------------|---|
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Very bad |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1065273 |

St Mary's Bow is shrouded by trees on a traffic island on the A11. The tower and chancel were built circa 1490 onto an early C14 nave. The south aisle was rebuilt in 1794, the upper tower in 1829 and restorations completed in 1848 and 1898-9. The upper tower was rebuilt and railings restored in the 1950s following World War II damage. The church suffers from extensive dampness, stone decay and leaking roofs. The church has been awarded a first round pass from the Heritage Lottery Fund for fabric repairs, a new drainage system and for tree management.

Contact: Ian Harper 020 7973 3786